

- \* 4÷20mA, 0÷1V, 0÷10V= 11(In); 10(gnd); 12(+)
- \* Pt100= 11 - 10(12) \* NTC, PTC= 11(In); 12(gnd)
- \* TcK, TcJ, TcS= 11(+)- 10(-)

